

**WO #:** PE69823

**WO Desc:** Auto valve after M1 meter B Leaking at the packing-LDAR

**Parent WO#:**

**WO Long Desc:** 1st attempt- tighten packing to stop leak

**WO Priority:** 1

**Location:** E-FE-M1-B

MONOMER FLOW ELEMENT

**Asset:** 1346910

MONOMER FLOW ELEMENT

**Asset Service:**

**Entry Date:** 7/25/2016

**WO Status:** CLOSE

**Action Code:** LDAR

**Project #:**

**Originator:** PAUL THOMPSON

**Status Date:** 1/24/2017

**Work Type:** CM

**Failure Class:** UNCLSS

**Job Plan:**

**Planned Start:**

**Actual Start:** 7/25/2016

**Review Date:**

**PM/Bundle:**

**Planned Completion:**

**Actual Completion:** 7/25/2016

### Plant Information

**RC:** PERC01

**Planner:** WILLIAM STONEKING

**MOC#:**

**When Code:** RT

**Lead Craft:** MECH

**MOC Status:**

**P&ID:**

**MOC Desc:**

**SIR/EIS Required:**

### LDAR

**Tag #:**

**1st Attempt Made:**

**LDAR Planning Notes:**

**Leak Type:**

**1st Attempt Was:**

**LDAR Additional Notes:**

**Size:**

**1st Attempt Due By:** 7/30/2016

**Leak Location:**

**After 1st Attempt PPM:**

**Location Orientation:**

**Final Due By:** 8/9/2016

### Work Order Notes

RICH WILLIAMS

07/25/2016

Tightened packing bolts.  
Notified Adam Chapman to check it.

RICH WILLIAMS

07/27/2016

Finally got confirmation to close the work order .

**Completed by Emp #:** \_\_\_\_\_

**Signature:** \_\_\_\_\_